

	Hits	Search Text	DBs
118	2	microdisplay same substrate same (CMOS near3 (driver IC chip (integrated adj3 circuit)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
119	6	microdisplay same substrate and (CMOS near3 (driver IC chip (integrated adj3 circuit)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
120	0	microdispla\$\$ and (mitigat\$6 adj3 defects)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
121	257	CMOS and LCD and (mitigat\$6)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
122	0	CMOS with LCD same (mitigat\$6)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
123	0	CMOS same LCD same (mitigat\$6)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
124	181	CMOS same (mitigat\$6)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
125	36	microdispla\$\$ and (mitigat\$6)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
126	156	(mitigat\$6 adj3 defects)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
127	0	(mitigat\$6 adj3 defects) same LCD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
128	4	(mitigat\$6 adj3 defects) and LCD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
129	0	(mitigat\$6 adj3 defects) and (bypass near3 latch)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
130	9	(mitigat\$6 adj3 defects) and (bypass)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
131	1176	(345/93,99,100).CCLS.	USPAT
132	111	S131 and (repaire\$2 test spare diagnos\$5)	USPAT

	Hits	Search Text	DBs
133	36	S131 and (repaire\$2 test spare diagnos\$5) and (latch bypass\$4)	USPAT
134	5	S131 and (repaire\$2 test spare diagnos\$5) and (bypass\$4)	USPAT
135	0	S131 and (repaire\$2 test spare diagnos\$5) and (latch same bypass\$4)	USPAT
136	32	S131 and (repaire\$2 test spare diagnos\$5) and (latch)	USPAT
137	1156	(repaire\$2 test spare diagnos\$5) and (latch same bypass\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
138	355	(repaire\$2 test spare diagnos\$5) same (latch same bypass\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
139	21	(repaire\$2) same (latch same bypass\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
140	175	(driver) same (latch same bypass\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
141	113	(driver) same (latch same bypass\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
142	28	(driver) with (latch with bypass\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
143	43	(driver) same (latch with bypass\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
144	15	S144 not S143	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
145	0	(defective near4 driver) same (latch same bypass\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
146	0	((defective fault\$4 bad) with driver) same (latch same bypass\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
147	10	((defective fault\$4 bad) with driver) and (latch same bypass\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
148	140	(345/93).CCLS.	USPAT

	Hits	Search Text	DBs
149	292	(345/90).CCLS.	USPAT
150	881	(345/98).CCLS.	USPAT
151	388	(345/99).CCLS.	USPAT
152	835	(345/100).CCLS.	USPAT
153	198	(345/206).CCLS.	USPAT
154	1352	(365/222).CCLS.	USPAT
155	172	(324/770).CCLS.	USPAT
156	363	(313/505).CCLS.	USPAT